## **ABM Panel** 28 Gauge Galvalume or Galvanized





Dot (•) identifies colors also available in 26 Gauge Galvalume



## There's good reason why we've been Heat Forming for more than a decade!

Heat forming practically eliminates a likely point of failure by significantly reducing the microscopic paint cracking and crazing during the forming process which may lead to paint failure and tension bend staining. Heating the panel before bending temporarily softens the paint which allows it to flex as the panel is formed and shaped.

## 

